U.S. Officials Only CONFIDENTIAL

SECURITY INFORMATION

CENTRAL INTELLIGENCE AGENCY

 	-		-	-
	$\Lambda = 1$			
i ez ivi	44 1 5		RFP	

25X1

SUBJECT Port and Harbor Facilities at Mezen

PLACE ACQUIRED

DATE ACQUIRED

25X1

DATE (of Info.)

This document contains information affecting the national defense of the united strates, within the meaning of title 16, sections 793 and 794, of the U.S. CODE, as amended. Its transition of Revelation of First Contents to or receipt by an Unauthorized Person is

THIS IS UNEVALUATED INFORMATION

RESPONSIVE TO					
1	2				
CD NO.					
00/C NO.					
ORR NO.					
DAS NO.		r"			
OCI NO.	1				

NO. OF PAGES 3

NO. OF ENCLS.

REPORT

SUPP. TO REPORT NO.

25X1

This report was obtained by the Department of the Nevy and is disseminated by CIA in accordance with paragraphs 3c of National Security Council Intelligence Directive #7.

1. Mezen is a lumber exporting port. The only modern equipment noticed was US-made "Ross Carriers," for the handling of lumber. Two pontoon wherees, one under construction, located at Ramanka, about four miles north of Mezen. No storage or warehouse facilities. A Port "Commissioner" handles all business dealings and is in charge of port security. A large amount of air activity noted in area. Lumber for export brought to Mezen by barge from hinterland.

Port Facilities

Mezen is located on the Mezen River, last of the entrances to the White Sea, at Lat 65° 52' No. Long 44° 17' E. There are no storage facilities at Mezen. A dirt road leads from the river bank up a hill to high level ground about a few stores and houses are located and where lumber is stacked availing shipment. Ships loading and unloading do so at Kamenka, a small sawmill town about four miles north of Mezen. This anchorage will hold about five ships the size of four or five thousand tons. A very good clay-holding ground was encountered here. Telephone and telegraph facilities were available.

3. Harbor - Entrance and Approaches

25X1

25X1

he requested permission to pass north of Morjovets
Island to avoid ice, but was denied permission. No ice breakers were
observed in the area during the time he was icebound in the narrow strait
between Morjovets Island and the mainland. he repeated radio
calls brought no answer. A few huts were observed on Morjovets Island, but
no people were sighted.

5

25X1

NAVY review

U.S. Officials Only

CONFIDENTIAL.

SECURITY INFORMATION

DISTRIBUTION → STATE X ARMY X NAVY X AIR X FBI CRR EV

Approved For Release 2007/06/19: CIA-RDP80-00926A006600010004-6

25X1

CONFIDENTIAL/US OFFICIALS ONLY SECURITY INFORMATION

- 2 -

4. Because of the 14' tide in the Mezen River, it can be entered only at high tide, which lasts ten hours, ebb tide lasting only two hours, due to the narrowness of the river and the very steep banks bordering it.

Navigational aids were stated to be very poor, both in the approaches to the Mezen River and in proceeding up the river. The channel is very narrow, barely wide enough to allow two ships to pass, and is marked by stakes or posts. There were very few lighted channel markers, but, source stated, the lack of lighted markers was of no concern because of the 24 hour daylight encountered at this latitude. No dredging or channel improvement was noted, nor were bridges or cables encountered. The river was estimated to be one half to one mile wide and very shallow, even at high tide.

25X1 high tide.

the river downstream from Mezen must be almost dry at low tide.

5. A pilot was taken aboard at the mouth of the Mezen River, and he remained aboard until ship left the Mezen River. The pilot boat was described only as a very modern, Diesel-powered craft.

6. Landing Facilities

There are no permanent quays, piers or docks due to the huge tides, strong currents and ice conditions. The only landing facilities whatseever consisted of two pontoon wharves secured in a parellel position to the shore by heavy chains and cables. Each wharf can load two ships at one time. These wharves are placed in the water in the spring and taken up in the fall. One wharf was completed and one under construction during the time ship was in port.

25X1

7. Port Administration

25X1

25X1

25X1

25X1

8.

Arendal is usinka, a see described again The port seemed to be under the complete control of weart "fort sides." with whom all business dealings were handled. Upon the arrival of ship, this Commissioner, in civilian clothes, boarded the ship with 25 or 30 uniformed men who searched the ship thoroughly, went through the personal effects of the men, and in the case of the Captain, read all his mail, particularly those letters written in English. The Commissioner was the only one who spoke English. Upon completion of the search, the crew of were given passes and permitted to go ashore at will; however, inasmuch as the village of Mezen was approximately four miles from the port, few men wandered out of sight of the ship, few of them willing to risk seizure. "Lorries" which appeared to be US-made autos of pre-World War II vintage, were available for transportation. No supplies or services of any kind were available. modern lumber-handling equipment in particular the very high, US-made automotive type vehicle which can straddle and lift a large pile of lumber at one time (Ross Carriers). These vehicles were present in goodly supply

25X1

at the pier, about ten uniformed men, or police, walked continuously up and down the pier, while one man stood watch at his gangway; and regardless of the number of times the Russian men loading the lumber used the gangway, each and every time they had to identify themselves to this guard, although obviously from the conversations that ensued these workmen were close friends of the guard. Other than these armed guards, no other police or soldiers were seen by

and carried the lumber from the large storage area on the high ground over-

looking the anchorage, down the sharp incline to the loading pier.

25X1


CONFIDENTIAL/US OFFICIALS ONLY SECURITY INFORMATION 25X1

25X1 25X1

25X1

25X1

25X1



Next 4 Page(s) In Document Denied

CONFIDENTIAL SECURITY INFORMATION PONTOON WHARF WEST BANK OF MEZEN RIVER WHARF SECURED TO SHORE BY CHAIN AND CABLES AND LOCATED ABOUT 42 MILES NORTH OF PORT OF MEZEN SHIP 600 PT. EST.

